CIVIL QUALITY CONSULTANTS & ENGINEERS

ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Name of Work : Comprehensive Development of Roads, Drains, Special repairs to buildings and other works in Sunnadagoodu, Ambedkarnagar, Mohan Kumar nagar, Poornapura, Ramabhovi Colony, Jalahalli Harijana, Siddarthanagar, Khathanagar, Ashrayanagar, Karadigudi, Peenya 4th block A K Colony and Surrounding areas of Slums in R R Nagar Constituency under PACKAGE- 2019-20 RRN-DIV-(13). BBMP, Bangalore

Name of Client	:	**Executive Engineer,** R R Nagar Division , BBMP, Bangalore.
Contractor/Agency	:	**Sri. N M Krishnamurthy,** Contractor, Bangalore.
Total Cost	:	Rs. 234.62 Lakhs
Date of Inspection	:	24.12.2021
Reference number	:	EE/RRND/Wo.No/000182/2020-21
Status of Bill	:	4th & Final Bill
In the Presence of	:	(a) **Assistant Engineer,** Ward No.17, BBMP, Bangalore.
	:	(b) **Mr. Mohan G,** Engineer M/S Civil Quality Consultants and Engineers, Bangalore

Compliance Report

Sl.No	Description of the Item	Unit	Qty		Comments / observations
1	Geophysical investigation of site for Sinking borewell for supplying drinking water to the	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
2	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
3	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
4	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
5	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
6	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
7	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.

Corporate Off: No. 193, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-56
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner

Sl.No	Description of the Item	Unit	Qty		Comments / observations
8	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
9	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
10	Sinking borewell of 165 mm dia clear using super fast hydraulic rig of capacity 300 PSIG &	Rmt	140.0	:	Work done upto the billed Quantity and Quality is satisfactory.
11	Providing and fixing 250mm dia PVC (casing pipe) As Per Direction of Engineer Incharge	Rmt	84.0	:	Work done upto the billed Quantity and Quality is satisfactory.
12	Supply of ISI Mark 175mm nominal Bore, Plain end steel casing Pipe-grade of steel Fee	Rmt	350.0	:	Work done upto the billed Quantity and Quality is satisfactory.
13	Providing 175mm Dia M.S. CollarAs Per Direction of Engineer Incharge	No	58.0	:	Work done upto the billed Quantity and Quality is satisfactory.
14	Providing 175mm dia Bore Cap CE (M) (As Per Direction of Engineer Incharge	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
15	Atalanta suguna CRI KIRLOSKAR and other equipments pumps 10.00	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
16	Providing and fixing in trenches galvinised/mild steel tube 50mm dia nominal bore with all	Rmt	2590.0	:	Work done upto the billed Quantity and Quality is satisfactory.
17	Supplying and drawing 3 core flat PVC sheathed submersible pump cable maufactured with	Rmt	5250.0	:	Work done upto the billed Quantity and Quality is satisfactory.
18	Providing and fixing in position 50mm Nominal bore non-return valve vertical type of	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
19	Spplying and fixing 50mm GI Union.As Per Direction of Engineer Incharge	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
20	Spplying and fixing 50mm GI Elbow.As Per Direction of Engineer Incharge	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
21	Spplying and fixing 50mm GI Nipple.As Per Direction of Engineer Incharge	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
22	Spplying and fixing 50mm GI Hose colleresAs Per Direction of Engineer Incharge	No	434.0	:	Work done upto the billed Quantity and Quality is satisfactory.

Scanned with CamScanner

CIVIL QUALITY CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited Laboratory as per ISO/IEC - 17025-2017

Testing of Construction Material - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item	Unit	Qty		Comments / observations
23	Supplying and fixing 20" x 20" x 2.5" polished wood board made of not less than 15mm	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
24	Supplying and fixing miniature circuit breakers on existing MCB distribution board using	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
25	Supplying of TPST with rewirable porcelain channels in SM encloser made out of 14	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
26	Supplying and fixing LED type panel board indicating lamp with required colour suitable	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
27	Suppling fully automatic star delta starter unit push button type with suitable wires 2	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
28	Supplying and fixing single phase preventer using necessary wires over an existing panel	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
29	Wiring for lighting/power circuit using one of FRLS PVC insulated 1100V grade	Mtrs	140.0	:	Work done upto the billed Quantity and Quality is satisfactory.
30	Supplying fixing and wiring heavy duty low voltage capacitors conforming to IS	No	28.0	:	Work done upto the billed Quantity and Quality is satisfactory.
31	Supplying, fixing, wiring, earth electrode for grounding conduits, I.C cotouts and other	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
32	Digging of trench of 0.36mtrs deepx0.5 mtrs wide refilling the trench to the required gorund	Mtrs	56.0	:	Work done upto the billed Quantity and Quality is satisfactory.
33	Supplying laying 1.1 KV class LT UG cable having aluminium conductor PVC	Mtrs	70.0	:	Work done upto the billed Quantity and Quality is satisfactory.
34	Labour charge for laying 1.1 KV class UG cable in existing trench GI pipe / stoneware	No	175.0	:	Work done upto the billed Quantity and Quality is satisfactory.
35	Supplying and fixing class-A(medium duty) GI pipe wall thickness not less then 3.25mm	Rmt	14.0	:	Work done upto the billed Quantity and Quality is satisfactory.
36	Supplying and fixing LT cast iron pot heads suitable for 1.1KV class UG cable filled	No	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
37	Supplying and fixing porcelain fuse channel with cut out on the existing wooden block and	No	21.0	:	Work done upto the billed Quantity and Quality is satisfactory.

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddabasti Main Road, Bangalore-
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.c

Scanned with CamScanner

CIVIL QUALITY
CONSULTANTS & ENGINEERS
ISO 9001:2015 Certified & NABL Accredited
Laboratory as per ISO/IEC - 17025-2017
Testing of Construction Materiol - Mechanical, Soil, Bitumen, Non Destructive Testing Services, Project Management Consultants, Third Party Quality Assurance, DPR.

Sl.No	Description of the Item	Unit	Qty		Comments / observations
38	Dismantling of cement concrete pavement by mechanical means using	Cum	107.5	:	Work done upto the billed Quantity and Quality is satisfactory.
39	Earthwork excavation for foundation of buildings, water supply, sanitary lines and	Cum	161.3	:	Work done upto the billed Quantity and Quality is satisfactory.
40	Providing and fixing Chorinated Poly Venyl Chloride (CPVC) pipes conforming to IS	Mtr	1195.0	:	Work done upto the billed Quantity and Quality is satisfactory.
41	Making connection of G.I.distribution branch with G.I.main of 25mm to 40mm.	Each	56.0	:	Work done upto the billed Quantity and Quality is satisfactory.
42	Providing and fixing Chorinated Poly Venyl Chloride (CPVC) pipes conforming to IS	Mtr	1540,1	:	Work done upto the billed Quantity and Quality is satisfactory.
43	Providing and fixing to wall, ceiling and floor Medium density polyethylene pipes 6.00	Mtr	1815.0	:	Work done upto the billed Quantity and Quality is satisfactory.
44	Refilling available around earth pipe lines,cables in layers mot exceeding 20cms in depth,	Cum	251.5	:	Work done upto the billed Quantity and Quality is satisfactory.
45	Providing and fixing in position brass gate valve with C.I.wheel of approved quality (screwed	Each	7.0	:	Work done upto the billed Quantity and Quality is satisfactory.
46	: Providing and fixing in position brass stop cock of approved quality 15mm	Each	280.1	:	Work done upto the billed Quantity and Quality is satisfactory.
47	Providing and laying in position plain cement concrete of mix 1:4:8 with OPC cement	Cum	176.4	:	Work done upto the billed Quantity and Quality is satisfactory.
48	Excavation for road, drains and similar works KSRRB 300-1. Earthwork excavation by	Cum	3169.9	:	Work done upto the billed Quantity and Quality is satisfactory.
49	Construction of granular sub-base Grading-V as Sub-base and drainage layer by providing	Cum	1057.1	:	Work done upto the billed Quantity and Quality is satisfactory.
50	Construction of dry lean cement concrete mix CC1:5:10 with OPC cement @160Kgs,	Cum	1057.1	:	Work done upto the billed Quantity and Quality is satisfactory.
51	Constructing un-reinforced, plain cement concrete for pavements using Grade	Cum	1057.1	:	Work done upto the billed Quantity and Quality is satisfactory.
52	Vaccum de-watering with vaccum pump and suction mat and compaction with skin	Sqm	7047.6	:	Work done upto the billed Quantity and Quality is satisfactory.

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

Corporate Off.: No. 133, Bhuvaneshwarinagar, Doddaballapur Main Road, Bangalore-560 05
Contact: 8553518550, 080-23240644 Email: civilqualityconsultants@gmail.com

Scanned with CamScanner